

Department of Toxic Substances Control
Project Status Update
For
Wyle Laboratories Norco Facility Site
July 2, 2004

SITE INVESTIGATION/CLEANUP DOCUMENTS

- DTSC issued comments on the Remedial Investigation Workplan to Wyle and is requiring significant modifications to the Workplan. DTSC received comments from the CAG today.
- DTSC continued its review of the draft Boundary Assessment Report. The Report documents boundary sampling activities and presents sampling results. The report does not include the additional soil gas sampling data collected along Golden West Lane.
- DTSC reviewed groundwater cleanup system effluent sampling results. The results indicated that no hazardous constituents were present in the treated groundwater. Consequently, DTSC informed Wyle that treated groundwater stored in tanks may be discharged to the creek.

INVESTIGATION/CLEANUP FIELD WORK

- Groundwater cleanup system operation is ongoing.
- Preliminary soil gas data collected from residential properties along Golden West Lane during the week of June 14, 2004 indicate trace to low levels of TCE in soil gas. The 100 microgram per liter screening level set by DTSC for TCE in soil gas was not exceeded in any of the samples on these properties. Soil gas data is undergoing data validation. Data will be released after completion of the data validation process.
- DTSC requested Wyle to develop and implement interim cleanup measures near its northwestern property boundary to address the source of contamination. An interim measures schedule will be developed within 30 days.

PUBLIC PARTICIPATION:

- DTSC staff visited residents along Golden West Lane who live on properties where soil gas samples were collected. DTSC handed the residents a fact sheet along with a figure that shows the preliminary results. DTSC staff explained the results and discussed future plans.
- DTSC is planning to hold a public meeting on August 17, 2004.